EXHAUST SYSTEM C

Ε

G

Н

J

Κ

L

Μ

CONTENTS

PREPARATION2	EXHAUST SYSTEM3	F
Special Service Tool 2	Removal and Installation3	
Commercial Service Tools 2		

EX-1

PREPARATION

PREPARATION


PFP:00002

EBS00DTK

EBS00DTL

Special Service Tool

The actual shapes of Kent-Moore tools may differ from those of special service tools illustrated here.




Commercial Service Tools

(Kent-Moore No.) Tool name		Description
(J-43897–18) (J-43897–12) Oxygen sensor thread cleaner	a Mating surface shave cylinder	Reconditioning the exhaust system threads before installing a new oxygen sensor (Use with anti-seize lubricant shown below.) a: J-43897-18 (18 mm) for zirconia oxygen sensor b: J-43897-12 (12 mm) for titania oxygen sensor
Anti-seize lubricant (Permatex 133AR or equivalent meeting MIL specifica- tion MIL-A-907)	AEM489	Lubricating oxygen sensor thread cleaning tool when reconditioning exhaust system threads

EXHAUST SYSTEM

Removal and Installation

Refer to the following figures for removal and installation.



PFP:20100


EBS00DTM

А

L


Κ

EXHAUST SYSTEM



CAUTION:

- Always replace exhaust gaskets with new ones when reassembling.
- For the QR25DE engine, install the front combination seal bearing as shown. Position the conical spring so that the wide end is against the flange as shown.



- With engine running, check all tube connections for exhaust gas leaks, and entire system for unusual noises.
- Check to ensure that mounting brackets and mounting insulators are installed properly and free from undue stress. Improper installation could result in excessive noise or vibration.
- Discard any heated oxygen sensor which has been dropped from a height of more than 0.5 m (19.7 in) onto a hard surface such as a concrete floor; replace it with a new one.
- Before installing a new oxygen sensor, clean exhaust system threads using oxygen sensor thread cleaner tool, J-43897-18 or J-43897-12, and apply anti-seize lubricant.
- Do not over-tighten the oxygen sensor. Doing so may cause damage to the oxygen sensor, resulting in the MIL coming on.